Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: LAKEWOOD 2-20H

Field Name: UPLAND Well File #: 21360

Date Incident:5/11/2015Time Incident:11:46Facility ID Number:County:DIVIDETwp:161Rng:96Sec:20Qtr:

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: Jon Breding

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well: Type of Incident: Treater Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 20 Barrels 20 Barrels 20 barrels

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 5/21/2015 Clean Up Concluded: 5/12/2015

Risk Evaluation:

None

Areal Extent:

Approximately 3 bbl. released outside of the berm affecting about a 20 ft. by 40 ft. area.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Contaminated material will be removed and replaced with clean fill.

Wastes Disposal Location: 13 Mile Disposal

Agencies Involved: Called John Rumppe @ 8:30 am 5/12/2015

Updates

Date: 5/13/2015 Status: Reviewed - Assigned to Other Agency Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained on location according to the report. NDIC retains oversight.